



X PHASE DUAL FORK
WALKING
FIG. 1 A




X PHASE INVERT Y DUAL FORK WALKING

FIG.1B




LINVERT X PHASE DUAL FORK WALKING

FIG.2A




LNVERT X PHASE INVERT Y DUAL FORK WALKING

FIG.2B




Y PHASE DUAL FORK WALKING

FIG.3A




Y PHASE INVERT X DUAL FORK WALKING

FIG.3B



INVERT Y PHASE DUAL FORK WALKING

FIG.4A



INVERT Y PHASE INVERT X DUAL FORK WALKING

FIG.4B





FIG.5



SYMBOL OF X PHASE WALKING

X PHASE WALKING

FIG.6A






FIG.6B




INVERT X PHASE WALKING

FIG.7A



INVERT X PHASE INVERT Y WALKING


FIG.7B



SYMBOL OF PHASE WALKING

Y PHASE WALKING

FIG.8A




Y PHASE INVERT X WALKING

V V V V V V V SYMBOL OF Y PHASE INVERT X WALKING

FIG.8B



INVERT Y PHASE WALKING



SYMBOL OF INVERT Y PHASE WALKING

FIG.9A



INVERT Y PHASE INVERT X WALKING

SYMBOL OF INVERT Y PHASE INVERT X WALKING




FIG.9B